



Prefeitura de
PAU D'ARCO DO PIAUÍ

NOTAS DE SERVIÇO - BUEIROS DO TRECHO 02
NOTA DE SERVIÇO - BUEIRO 01

Rodovia:

Trecho:

Sub-trecho:

Estaca + fração	Offset esquerdo			Bordo esquerdo		Cota			Bordo direito		Offset direito		
	Dist.	Cota	Cob	Dist.	Cota	Terreno	Eixo	Vermelha	Dist.	Cota	Dist.	Cota	Cob
E102	-3,258	135,172	0,230	-3,000	135,402	136,392	136,592	0,200	3,000	135,402	3,156	134,029	1,373
E103	-3,856	134,823	0,452	-3,000	135,275	134,711	135,426	0,715	3,000	135,275	3,869	134,026	1,249
E103+12,00	-4,215	134,022	1,167	-3,000	135,189	134,215	135,370	1,155	3,000	135,280	4,729	134,125	1,155
E104	-4,125	134,015	1,143	-3,000	135,158	134,155	135,371	1,216	3,000	135,281	4,775	134,520	0,761
E104+10,00	-4,963	134,000	1,385	-3,000	135,385	134,025	135,375	1,350	3,000	135,285	4,995	134,256	1,029

NOTA DE SERVIÇO - BUEIRO 02

Rodovia:

Trecho:

Sub-trecho:

Estaca + fração	Offset esquerdo			Bordo esquerdo		Cota			Bordo direito		Offset direito		
	Dist.	Cota	Cob	Dist.	Cota	Terreno	Eixo	Vermelha	Dist.	Cota	Dist.	Cota	Cob
E152+15,00	-4,500	139,889	0,912	-3,000	140,801	139,983	140,191	0,208	3,000	140,801	4,017	140,123	0,678
E153	-3,021	140,040	0,525	-3,000	140,565	140,230	141,350	1,120	3,000	140,565	3,282	140,377	0,188
E154	-3,252	140,195	0,177	-3,000	140,372	140,262	141,159	0,897	3,000	140,372	3,071	140,325	0,047
E155	-3,002	141,954	0,164	-3,000	142,118	142,008	142,211	0,203	3,000	142,118	3,087	142,061	0,057